Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 12/15/2015, 12/16/2015, 12/17/2015	Man Days: 3
Inspection Unit: Champaign	
Location of Audit: Champaign	
Exit Meeting Contact: John Sigler	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	
·	

CONSTRUCTION INFORMATION			
Location of Construction:		Construction Perfo	ormed By:
605 West Michigan Street, Urbana, Illinois		Ameren Illinois Crew	V
Contractor Foreman:	No contractor on this job		
Operator Inspector:	John Sigler, Quality Assurance		
	Person(s) On J	ob Site	
Robert Bell	Dan Zwillin	ng	Jordan Frerichs
Alan Harmon	Jason Little	е	Brett Harris

Description of Construction:

Ameren Illinois crew was installing a new plastic service line to 605 West Michigan Street, in Urbana, Illinois. The service line was a 1 inch Driscoplex pipe, ASTM D-2513, PE 2406/2708, and air tested to 102 # for 10 minutes, with no leaks being found.

SERVICE INSTALLATION		Status
[192.55]	Steel	No
General Comment:		
No steel pipe was installed during this audit.		
[192.59]	PE	Yes
General Comment:	•	•
The pipe was 1 inch Driscoplex pipe,		
[192.59]	Other	No

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
No other pipe was installed.		
[192.619,192.621,192.623]	MAOP	60#
[192.5]	Class location :	Class 3
[192.53]	Are components qualified for use?	Satisfactory
General Comment:		
All components were qualified to use on this job.		
[192.63(a)(2)]	Pipe Size :	1 inch
[192.55,192.59]	Specification :	ASTM D-2513
[192.55,192.59]	Manufacturer:	Driscoplex
[192.55,192.59]	Pipe Grade :	2406/27608
[192.55,192.59]	Wall Thickness :	.099 wall
[192.63]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
General Comment:		
The pipe and all fittings were properly marked.		
[192.227]	Welder qualification date:	Not Applicable
General Comment:		
No welder was on this job.		
[192.227]	Welder's Name:	Not Applicable
General Comment:		
No welder was on this job.		
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Satisfactory
General Comment:		
Pipe was joined according to O&M procedures.		
[192.285]	Date of Qualification :	2-4-15
[192.285]	Joiner's name:	Dan Zwilling
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
There was no buried metallic pipe at this job site.		
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
•		

AMEREN ILLINOIS COMPANY/12-17-2015

Page 2 of 6

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

No cathodic protection at this job, the piping was all plas	stic.	
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
General Comment:		
This is an all plastic system.		
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
General Comment:		
This is an all plastic system.		
[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
This is an all plastic system.		
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:		
This is an all plastic system.		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Satisfactory
General Comment:		
The above ground facilities were clean and coated at the	is job site.	
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
No underground metallic structures were located in this	area.	
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
General Comment:		
The ditch was back filled to provide support to the new p	pipe that was installed,	
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
General Comment:		
A protective sleeve was installed at the tapping tee to pr	rotect the piping that was fused into the tapping tee.	
[192.321]	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:		
Tracer wire was installed alongside the new service line	that was installed.	
[192.327(a)]	Is required cover being obtained for the service line?	Satisfactory

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
Required cover was maintained at a depth	of 36 inches.	
[192.503]	Are general testing requirements being met?	Satisfactory
General Comment:	· ·	
The new service line and tap was air tested	to 102# for 10 minutes with no leaks being found.	
[192.517]	Are records being made of strength and leak tests?	Satisfactory
General Comment:		
Records are being maintained of the streng	gth and leak test.	
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
General Comment:		
OQ records were inspected for qualification	ns of the employees on the job site.	
[192.805(c)]	Were non-qualified personnel being directed and observed by a qualified individual?	Satisfactory
General Comment:		
Non-qualified employees were being direct	ly observed by qualified employees.	
[192.805(c)]	Were span of control limitations being followed?	Satisfactory
General Comment:		
Span of control was being followed, by one	on one observation.	
Was a Protocol 9 (Form 15) Comp	leted?	No
General Comment:	·	
A protocol 9 was not completed at this time	2.	
[192.614]	Were One Call Notifications performed as required?	Satisfactory
General Comment:		
The Ameren crew had a Julie number for the	nis job.	
[192.614]	Dig Ticket #	A003360219
[192.383(b)]	Is an EFV installed on any new or replaced service line serving a single-family residence?	Satisfactory
General Comment:		
An EFV valve was installed at the tapping t	ree.	
[192.751]	Are adequate steps taken to minimize the potential for accidental ignition?	Satisfactory
General Comment:	<u>'</u>	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Steps were taken to minimize accidental ignition.

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.